

Installation Instructions  
For all 3-M tape products.

The ideal temperature for applying  
The 3M tape products is 60°F to 100°F

All surfaces must be cleaned  
with isopropyl alcohol. Peel the  
plastic covering from the tape.  
Carefully align then stick  
the product to the mating surface.

Installation Instructions  
For all 3-M tape products.

The ideal temperature for applying  
The 3M tape products is 60°F to 100°F

All surfaces must be cleaned  
with isopropyl alcohol. Peel the  
Plastic covering from the tape.  
Carefully align then stick  
The product to the mating surface.

Installation Instructions  
For all 3-M tape products.

The ideal temperature for applying  
The 3M tape products is 60°F to 100°F

All surfaces must be cleaned  
with isopropyl alcohol. Peel the  
plastic covering from the tape.  
Carefully align then stick  
the product to the mating surface.

Installation Instructions  
For all 3-M tape products.

The ideal temperature for applying  
The 3M tape products is 60°F to 100°F

All surfaces must be cleaned  
with isopropyl alcohol. Peel the  
Plastic covering from the tape.  
Carefully align then stick  
The product to the mating surface.

Installation Instructions  
For all 3-M tape products.

The ideal temperature for applying  
The 3M tape products is 60°F to 100°F

All surfaces must be cleaned  
with isopropyl alcohol. Peel the  
plastic covering from the tape.  
Carefully align then stick  
the product to the mating surface.

Installation Instructions  
For all 3-M tape products.

The ideal temperature for applying  
The 3M tape products is 60°F to 100°F

All surfaces must be cleaned  
with isopropyl alcohol. Peel the  
Plastic covering from the tape.  
Carefully align then stick  
The product to the mating surface.